CONFIDENTIAL FORM GC1

# GRID CODE MODIFICATION RECOMMENDATION FORM



MPID 267 Housekeeping Modification - Failure to Follow Notice to
Synchronise Instruction
MPID 267
GCRP Meeting #04/2015 – 02 December 2015
Definitions
Version 6
Grid Code Modification Proposal MPID 223 was approved by CER on 28 <sup>th</sup> September 2015. MPID 223 changed the time allowed for a <b>Generation Unit</b> to synchronise, from 5 minutes, to 15 minutes, after the <b>Synchronising</b> time. However the definition <b>Failure to Follow Notice to Synchronise</b> was not updated to reflect this change. The purpose of this modification (MPID 267) is to align the definition <b>Failure to Follow Notice to Synchronise</b> with the approved MPID 223.
MPID 267 was proposed and agreed at the GCRP meeting #04/2015 that took place in Belfast on 2 December 2016.
No objections were noted.

CONFIDENTIAL FORM GC1

Outcome of any GCRP Meeting Actions Relating to the Recommended Modification	It was agreed that the TSO submit a recommendation paper to the CER.
Implication of not implementing the Modification	Possible confusion as to when the Failure to Follow Notice to Synchronise Instruction should be issued.

# **RED-LINE VERSION**

## **DEFINITIONS**

# Failure to Follow Notice to Synchronise Instruction

An instruction given by the **TSO** to a **Generator** in respect of its **CDGU** confirming that it has failed to **Synchronise** more than 5 15 minutes after the time specified in the **Notice to Synchronise**.

## **GREEN-LINE VERSION**

## Failure to Follow Notice to Synchronise Instruction

An instruction given by the **TSO** to a **Generator** in respect of its **CDGU** confirming that it has failed to **Synchronise** more than 15 minutes after the time specified in the **Notice to Synchronise**.