

MODIFICATION PROPOSAL FORM

160 SHELBOURNE ROAD
BALLSBRIDGE

DUBLIN 4

PH: +353-1-677 1700

FAX: +353-1-6615375

EMAIL: GRIDCODE@EIRGRID.COM

FORM GC1, PROPOSAL OF MODIFICATION TO GRID CODE.

MODIFICATION PROPOSAL ORIGINATOR:	EIRGRID		
MODIFICATION PROPOSAL ORIGINATOR (CONTACT NAME)	ANNE TROTTER	MODIFICATION PROPOSAL ORIGINATOR FAX NUMBER:	+353-1-6615375
MODIFICATION PROPOSAL ORIGINATOR TELEPHONE NUMBER:	(01) 2370348	DATE:	17 TH NOVEMBER 2015
MODIFICATION PROPOSAL ORIGINATOR E-MAIL ADDRESS:	anne.trotter@eirgrid.com	MODIFICATION PROPOSAL NUMBER (EIRGRID USE ONLY)	MPID 267
GRID CODE SECTION(S) AFFECTED BY PROPOSAL:	DEFINITIONS		
GRID CODE VERSION :	6.0		

<p>MODIFICATION PROPOSAL DESCRIPTION</p> <p>(MUST CLEARLY STATE THE DESIRED AMENDMENT, ALL TEXT/FORMULA CHANGES TO THE GRID CODE. THE REQUIRED REASON FOR THE MODIFICATION MUST STATED. ATTACH ANY FURTHER INFORMATION IF NECESSARY.)</p>	<p>Grid Code Modification Proposal MPID 223 was approved by CER on 28th September 2015. MPID 223 changed the time allowed for a Generation Unit to synchronise, from 5 minutes, to 15 minutes, after the Synchronising time. However the definition Failure to Follow Notice to Synchronise was not updated to reflect this change. The purpose of this modification (MPID 267) is to align the definition Failure to Follow Notice to Synchronise with the approved MPID 223.</p> <p><u>Red-line Version:</u></p> <p>DEFINITIONS</p> <p>Failure to Follow Notice to Synchronise Instruction</p> <p>An instruction given by the TSO to a Generator in respect of its CDGU confirming that it has failed to Synchronise more than 5 15 minutes after the time specified in the Notice to Synchronise.</p> <p><u>Green-line Version:</u></p> <p>DEFINITIONS</p> <p>Failure to Follow Notice to Synchronise Instruction</p> <p>An instruction given by the TSO to a Generator in respect of its CDGU confirming that it has failed to Synchronise more than 15 minutes after the time specified in the Notice to Synchronise.</p>
<p>IMPLICATION OF NOT IMPLEMENTING THE MODIFICATION</p>	<p>Potential for confusion as to when the Failure to Follow Notice to Synchronise Instruction should be issued.</p>
<p><i>Please submit the Modification Proposal by fax, post or electronically, using the information supplied above</i></p>	
<p>EIRGRID REVIEWER</p>	
<p>EIRGRID ASSESSMENT</p>	